

INVESTIGATION ON SERVICE YEARS OF LARGE RUBBER MARINE FENDERS

Hitoshi AKIYAMA¹, Kentaro SHIMIZU², Shigeru UEDA³ and Toshiro KAMADA⁴

¹Member of JSCE, Dept. of Civil Eng., Osaka University (2-1 Yamadaoka, Suita-shi, Osaka 565-0871, Japan)
E-mail: hitoshi.akiyama@bridgestone.com

²Marine Fender Developments, Bridgestone Corporation (1 Kashio-cho, Totuka-ku, Yokohama 244-8510, Japan)
E-mail: kentaro.shimizu@bridgestone.com

³Fellow Member of JSCE, Professor emeritus, Tottori University
(2-2-2 Hayabuchi, Tsuzuki-ku, Yokohama 224-0025, Japan)
E-mail: ued21010@ideacon.co.jp

⁴Member of JSCE, Professor, Dept. of Civil Eng., Osaka University
(2-1 Yamadaoka, Suita-shi, Osaka 565-0871, Japan)
E-mail: Kamada@civil.eng.osaka-u.ac.jp

Estimating the life of rubber marine fender (fender) is an important concern in the maintenance of a port facility. From the supply record of the Circular-Shaped Buckling (CSB) fender with panel contact, the actual service life was from 15 to 35 years. The compression tests of the fenders returned from ports showed that the reaction forces increased moderately due to the years in service. Other than some visible signs such as cracks and deformations, invisible signs of aging including uneven buckling, increased reaction force, and the growth of cracks were observed. The material tests results indicated that the deterioration of physical properties were limited to the rubber surface; the center of rubber bodies were still considered to be elastic and flexible. The performance in the first compression cycle of the test showed that the used fender exhibited a higher reaction force than the value stated in the catalogue - that is a value equivalent to the average of the second and third compression cycles. This increased reaction force during the first compression cycle (after a long interval from its last compression cycle), for example, if used as inventory stock, could potentially be a concern to the berth structure and/or the vessel's hull.

Key Words : rubber fender, durability, service years, failure modes, compression test, field survey

1. INTRODUCTION

A fender is primarily a damper installed on the quay wall in order to absorb the large kinetic energy of a berthing ship. Before fender was developed approximately 60 years ago, timbers and old tires were used for this purpose. Since then, fenders have increased in size and type considerably in order to cater to the growing size and range of ships. This has also led to the importance of maintenance of the port infrastructure. Unfortunately, the number of studies for service life of fenders is limited. Terauchi et al.¹⁾ reported that the service life of V-shaped fenders was from around 10 to 20 years. This was based on verification, by the inspection of various fenders in ports around Japan. A maintenance guideline²⁾ was published to evaluate the remaining function of fenders by measuring the visible defects of the fender body. However the actual replacement record of large-sized fenders has not been open and no practical barometer




Fig.1 The Circular Shaped Buckling (CSB) fender system.

of service years exists. The unexpected failure of fenders will affect not only the cost but also the safe

operation of a port facility. The appropriate life forecast of fenders is important. Authors looked through the supply records of the CSB fender, with frontal panel, and studied the reason for their replacements to better understand the aging effects that had resulted.

Fig.1 shows the general concept of the CSB-type fender system. The frontal panel is mounted and fixed onto the thick vertical rubber cylinder, through an embedded steel flange by nut and bolt; the weight of the frontal panel is supported by chains. The quay side of flange is fixed to the quay wall by anchor bolts. The CSB fender, which was developed in 1964, range from 400mm (400H) to 3m (3000H) in size. The total number of fenders sized 2000H and above is approximately 1900 units globally.

Fig.2 illustrates the reasons for fender replacements and the factors for deterioration. The term ‘service years’ is defined as the years between delivery and removal of the fenders. The reason for replacement due to the external deterioration can be visually evaluated by the maintenance guideline²⁾. In the case that fenders are deteriorating internally, therefore not visible, it becomes a hidden risk unless it is replaced as part of preventive maintenance. The items in the red box in **Fig.2** are the non-visible forms of deterioration as focused on in this paper. The fender life is determined by both visible and non-visible deteriorations. The deteriorations are caused by the environmental and operational conditions. Sulfur crosslinks in rubber break up by oxidation and become stiffer after they re-entangled, but strain such as abnormal compression also damage those linkings. As a result, the elasticity could both increase and decrease. As an environmental factor, hardening by age causes high reaction force, which could be a concern to the berth structure and ship’s hull. Embrittlement of rubber could grow cracks on the surface and tear the rubber body. Note that cracks on surface are closed and not clearly visible when the fender is not compressed. They open when the fender is compressed and will tear and increase in size if the rubber deteriorates. These factors, combined with operational factors, determine the physical life of the fender.

This paper aims to clarify the actual service years of fenders and evaluate the deterioration to determine the physical life as a large rubber product in marine use. In Chapter 2, the profile of the number of unit was demonstrated in terms of service years, reason for replacement, type of ship, and type of berth structure. In Chapter 3, the compression test result of returned fenders is shown and the deterioration of fender is explained. In Chapter 4, the result of material tests derived from the dissected rubber body is discussed.




Fig.2 Reasons for fender replacement and factors.




Fig.3 Summary of fender replacements.

2. ACTUAL SERVICE YEARS

In this chapter, the replacement projects of CSB fenders (sized 2 meters and above) were selected from our delivery record. The number of projects is categorized into reasons, ship types, and berth types.

The number of replacement by reasons are shown in the left column of **Fig.3**. “Upgrading” means that the replacements were required to facilitate larger ships. “Abnormal impact” refers to the damage caused by ships with abnormal speed or motion. The excessive berthing velocity causes the over compression and sulfur cross-linking inside rubber are cut thus the performance decreases. Also the abnormal berthing angle causes the uneven buckling. Thus fenders may be replaced if those accidents were reported. “Visible deterioration” is the replacement by visual inspection based on the maintenance guideline²⁾. “Preventive” means fenders were replaced before they showed any sign of damage in order to keep the safety operation of the berth. The “Aging” has two peaks at 15 to 19 years and at 30 to 34 years while there are no clear peaks in “Upgrading” and “Abnormal impact.” The center column in **Fig.3** shows the

number of replacements at each age in relation to ship types and the right column indicates berth types. The ships with fenders larger than 2 meters are generally transporting crude oil tankers or bulk cargo. In this survey, 83% of crude oil tankers use dolphin arrangement. Thus the profiles of dolphin and crude oil tanker, look similar to those of the bulk cargo and quay. The cumulative percentage indicates that 90.1% of replacements are conducted before 35 years of use.

Thus, it is concluded that the actual service years from replacement record is 15 to 35 years. Fenders situated on dolphins are likely to be changed earlier than fenders situated on a quay. Each fender had different conditions which should affect its life such as climate, geographical location, and maintenance level. The individual arrangements will be discussed in more detail in Chapters 3 and 4.

3. COMPRESSION PERFORMANCE OF USED FENDERS

A number of the used sample fenders were laboratory tested for quality when removed. In this chapter, the performances of these fenders were discussed to see how the age had changed and differed from the catalogue performance.

(1) List of returned fenders

Though the opportunity to use the old fenders tested under laboratory conditions was very limited, we managed 26 fenders in all, as shown in **Table 1**. Individual causes for replacement are also noted with short remarks. Degradation points are explained in **Table 5** at the end of section (3).

Table 1 List of returned fenders.

 Degradation points > 6 (Non usable)

FD No.	Ship type	Fender size	Units	Delivered in	Service years	T (°C)	Reason of replacement	Remarks (Non-visible deteriorations)	Degradation Points
		Rubber Grade		Tested in					
1	Crude oil Tanker	1600H (R1)	2	2010 2011	1	13.4	Over compressed by tsunami of East Japan Earthquake	Cuts by fixing bolts but still kept good performance	2
2	Crude oil Tanker	1600H (R1)	2	2001 2011	10	13.4	Over compressed by tsunami of East Japan Earthquake	Cuts by fixing bolts (Abnormal impact) but still kept good performance.	2
3	Bulk cargo	1450H (R0)	2	1992 2006	14	23.1	Visible deterioration-cracks(0.5-1.3m), Cuts by fixing bolt	Material test, Uneven buckling, High reaction force (+15%)	18
4	Crude oil Tanker	1450H (RH)	1	1982 1997	15	15.7	Visible deterioration-cracks, Steel exposition and rust	No temperature record (assumed 23°C)	3
5	LNG Carrier	2000H (R0+10)	1	1988 2009	21	15.2	Preventive maintenance	Material test, Light uneven buckling, Surface cracks.	4
6	Pontoon	800H (RH, R1)	2	1992 2014	22	15.8	Preventive maintenance (with Pontoon maintenance)	High reaction force (+13%) but still kept good performance	3
7	Pontoon (Oil barrier)	630H (RH)	1	1992 2014	22	16.8	Preventive maintenance	High reaction force (+10%) but still kept good performance.	3
8	Car Carrier	800H (R0)	2	1981 2006	25	17.0	Visible deterioration-steel exposition and rust	Material test, Uneven buckling.	9
9	LNG Carrier	1700H (RE)	1	1983 2010	27	15.7	Preventive maintenance	Material test, Surface crack but kept good performance.	3
10	LNG Carrier	2000H (R1)	4	1977 2007	30	15.2	Preventive maintenance	Material test, Surface crack, High reaction force (+23%)	6
11	Crude oil Tanker	3000H (R0-10)	1	1975 2007	32	15.2	Preventive maintenance	Material test, Test discontinued by severe cracks and uneven buckling.	18
12	Bulk cargo	1000H (R0)	2	1978 2010	32	16.4	Visible deterioration-steel exposition and rust. Cuts by abnormal impact.	Severe cracks, Test discontinued by too high reaction force (+56%).	18
13	Crude oil Tanker	2250H (R0)	1	1971 2010	39	16.4	Visible deterioration-cracks of abnormal impact and upgrading.	High reaction force (+11%), Light uneven buckling.	9
14	Crude oil Tanker	3000H (R0-10)	1	1974 2013	39	15.2	Visible deterioration-cracks	Test discontinued by uneven buckling, cracks and high reaction force (+20%)	12
15	Bulk cargo	1000H (R0)	2	1970 2010	40	16.4	Visible deterioration-cracks	Test discontinued by too high reaction force (+37%) and severe cracks.	18
16	Crude oil Tanker	2000H (R1)	1	1970 2012	42	15.2	Visual deterioration-cracks.	Test discontinued by extreme uneven buckling.	18

Note : "Material aging" means the fender was dissected for material tests.

Temperature was not recorded for FD No.4, 5, 8, 10, and 14 so the average temperature record³⁾ :T was used.

The rubber grade is the grade of hardness in order as: RE > RH > R0+10 > R0-10 > R1

Degradation Points is the degree of degradation explained in **Table 5** (non usable over 6 points with red circle)

(2) Performance and deformation

Table 2 shows the performance curves for mid-sized to large fenders based on 10-year intervals. The performance results for the first compression cycle test are expressed in blue dots and dashed lines. The average of the second and third compression cycle are expressed in red dashed lines. The average of the second and third compression cycle

are in red dashed lines. The catalogue values are in black solid lines. “The average of the second and third compression is used as a standard performance which must be within $\pm 10\%$ deviation of catalogue’s value.

Table 2 Performances of fenders in 10-year generations.

○ Non usable

Size Generation	Large fenders over 1600H				Mid-size fenders smaller than 1600H			
0 year (New)	2500H(R0)	Bulk cargo	0 year	-	1000H(R0)	LNG Carrier	0 year	-
10 to 19 years	1600H(R1)	Crude oil tanker	10 years	FD No.2	1450H(R0)	Crude oil tanker	14 years	FD No.3 ○
20 to 29 years	2000H(R0+10)	LNG Carrier	21 years	FD No.5	800H(R0)	Car carrier	25 years	FD No.8 ○
30 to 39 years	3000H(R0-10)	Crude oil tanker	32 years	FD No.11 ○	1000H(R0)	Bulk cargo	32 years	FD No.12 ○
Over 40 years	2000H(R1)	Crude oil tanker	42 years	FD No.16 ○	1000H(R1)	Bulk cargo	40 years	FD No.15 ○

Table 3 Photos of cracks and bucklings under compression.

Cracks under compression			
	Degradation point : 2 Surface cracks at 40% compression 2000H, 30 years: FD No. 10	Degradation point : 3 Severe cracks at 20% compression 3000H, 32 years: FD No. 11	Degradation point : 6 Severe cracks and tear at 30% comp. 1000H, 40 years: FD No. 15
Buckling shape under compression			
	Degradation point : 0 Normal buckling at 45% compression 1600H, 10 years: FD No. 2	Degradation point : 3 Light uneven buckling at 50% comp. 2000H, 21 years: FD No. 5	Degradation point : 6 Extreme uneven buckling at 45% comp. 2250H, 42 years: FD No. 16

The compression test procedure was based on the PIANC 1980 guidelines⁴⁾ as follows:

1. Total 3 times compression with about 5-minute intervals at the speed from 2 to 8cm/s.
2. The first compression is called the stress relaxation cycle and data are ignored.
3. The average of second and third values are regarded as the standard value.

Zero (0) year is the example of the shipping inspection tests of a new product. Note that the 1600H- (FD No.2) sized fender was included in the large sized category owing to lack of record of a fender larger than the 2000H in 10 to 19 years section. The red circle at the upper right corner indicates that the fender is regarded as unusable.


Since those tests have been conducted over such a long period, old figures were converted to a common expression in the following manner:

1. The performance is affected by temperature. Thus performances are corrected to 23 °C by temperature factors. If test temperature had not been recorded, the average temperature of the day of testing in the Japan Meteorological Agency website³⁾ was used. If even the test date was unknown, 23°C was assumed (FD No.4).
2. All dimensions were converted to the SI unit assuming the gravity was 9.81m/s².

(3) Deterioration modes under compression

Here, visual and non-visual symptoms of aging are explained. **Table 3** provides examples of the growth of cracks and the buckling effect when the fenders were compressed. In coastal areas, oxygen and ozone break the polymer links by destroying the hydrogen

Table 4 Reasons of uneven buckling.



molecules from the surface of the rubber. Skin rubber loses its flexibility and cracks open when the outer surface is stretched by fender compression. The body rubber (under the skin) also deteriorates and becomes harder and inflexible. Thus, the surface cracks become larger throughout the whole body. The upper right photo in **Table 3** shows the expanded crack prior before the test was stopped. These cracks occur mainly on the upper side of the body where the rubber has more sunlight. “Uneven buckling” is the asymmetric deformation when the fender deforms sideways. As a result, the reaction force reduces after the peak as shown in FD No. 12 and FD No. 16 in **Table 2**. The reduction of reaction force would reduce the energy absorption. There are many reasons for uneven buckling other than abnormal angular berthing as stated in Chapter 2. The weight of fender body and frontal panel always pulls the top of fender downwards especially when the weight support chains are loose as shown in the left photo in **Table 4**. Also the protrusion of the ship belt sometimes pushes the

Table 5 Degradation points of each mode.

Degree	Light	Medium	Severe
Modes			
Crack length	2	3	6
Uneven buckling	2	3	6
High reaction force rate: C_R	0	3	6
Test discontinued	6		

Points bigger than 6 is non-usable.

$R_m = \alpha \times n + 0.1$ (α : Gradient of C_R , n : Service years)

frontal panel down while the ship is moored and loading cargo, which is shown in the right photo in **Table 4**. The vertical permanent deformation is recommended by the manufacturer to be less than 3% of fender height to maintain the performance. These factors could shorten the actual service life, therefore both physical and chemical consideration in design, operation, and maintenance are very important. In **Table 2**, the tests after 30 years were discontinued mainly by uneven buckling for large fenders, and by the increases in the cracks for mid-sized fenders. These fenders were now performing too far from their original specification and therefore deemed unusable; the decision to replace the fenders was proven correct. The uneven buckling observed at FD No.5 (2000H, 21 years) was very minor. It was reported that this fender was rotated 180 degrees in order to cancel the asymmetry of gravity and sunlight. This consideration should have improved the service life of this fender. Another exception is FD No.3 which showed uneven buckling and 15% increase in reaction force after only 14 years. This berth is located in the south island of Japan where the average temperature is 23°C which is from 7 to 8 °C higher than in other parts of Japan³) as shown in **Table 1**. High temperatures accelerated the aging of FD No.3. This will be discussed further in Chapter 4. The rate of material aging by external factors such as sunlight and oxygen of large-sized fenders is slower than mid-sized fenders due to the rubber thickness. Therefore, the increase in reaction force of large fenders is relatively small. On the other hand, according to a simple beam theory, assuming the fender is mounted to the quay in the normal horizontal fashion, the vertical (drooping) deflection effect at the frontal panel end is relative to scale and therefore the larger the fender/frontal frame is, the greater the drooping effect. This is one of the reasons why the uneven buckling was more evident in large fenders. In **Table 2**, the reaction forces of mid-sized fenders exceeded the 10% manufacturing tolerance after 30 years. The uneven buckling may reduce the reaction force potentially canceling out the rubber hardening in large




Fig.4 Reaction Force Coefficient by age: C_R
(Average of 2nd-3rd compression at 25%).

fenders, but it should be warned that there are non-visible aging effects other than reaction force and 30 years is a reasonable time for replacing fenders.

The deterioration point is defined as shown in **Table 5** in which the fender scoring more than 6 points is considered “Non-usable”. The basis of these points is from visual evaluation explained in the maintenance guideline²). R_m in **Table 5** is defined as the total of aging impact and 10% manufacturing tolerance.

(4) Reaction force coefficient by age: C_R

For instance, dolphins and piers supported by piles are sensitive to horizontal load thus the maximum fender reaction force is used for the design criteria. Therefore, it is important to estimate the years until the reaction force exceeds the design load to determine the service years of fender. In **Table 2**, the tendency of the reaction force by age is not clear because they differ by size, rubber grades and manufacturing tolerance ($\pm 10\%$). Thus, the Reaction Force Coefficient: C_R is defined as follows;

$$C_R = R_P/R_S \quad (1)$$

C_R : Reaction force coefficient.

R_P : The peak reaction force of used fenders.

R_S : The rated reaction force at 25% deflection of standard performance.

Fig.4 shows the reaction force coefficient by service years. The average of C_R plots indicates a slight increase with a tendency to spread to the right; this is relative to the number of years in service. The blue inclined square plots are mid-sized fenders smaller than 2m in height and the red square plots means large-sized fenders over 2m high. The plot with red circle means the fender was judged already unusable based on the degradation points in **Table 5**. FD No.11

(32 years), No.12 (32 years), No.15 (40 years), and No.16 (42 years) were also non-usable but not plotted in **Fig.3** as they could not be compressed three times. The average annual rate of 0.483% per year is based on the assumption that the initial value was 1.0, per the catalogue value. The maximum serviceable years obtained from the test results was approximately 30 years with two exceptions; the smaller-sized FD No.4 and FD No.8 because they showed uneven buckling and the signs of abnormal berthing (cut by the fixing bolt and exposed steel). Thus, the past abnormal berthing is supposed to be the reason for these early uneven bucklings rather than the dead weight of the frontal panel. The red dashed lines are upper and lower limit of 99% confidence interval. Conventionally, they are two straight lines running parallel to the average regression line. The plots indicate a spread towards the right and an increase in the deviation by the number years. The environment and conditions of use are different in every fender, thus it is understood that the range of variance spreads wider by service years. It is reasonable to express the confidence values by extending the range of variance in relation to service years. To simplify the phenomenon, the variance was assumed to increase by service years and the maximum likelihood method was used. The increasing variance is expressed by equation (2):

$$\sigma_n = \exp(\beta_0 + \beta_1 x_n) \quad (2)$$

Here,

- σ_n : Variance of C_R at x_n
- β_0 : Y-intercept of variance
- β_1 : First constant of variance
- x_n : Service years

Now, the probability of x_n as the Normal distribution is assumed by equation (3):

$$f(x_n) = \frac{1}{\sqrt{2\pi\sigma_n^2}} \exp\left(-\frac{(x_n - \mu)^2}{2\sigma_n^2}\right) \quad (3)$$

Table 6 Values of parameter β .

Confidence Value	β_0	β_1	β_2
99%	-3.4719	0.0385	2.5758

Table 7 Reaction force coefficient by years:
(Constant variance and increasing variance).

Service years		10	20	30	40	50
Average		1.05	1.09	1.14	1.19	1.24
99% Confidence Interval with constant variance	Variance: σ	0.09	0.09	0.09	0.09	0.09
	Upper limit	1.27	1.32	1.37	1.42	1.47
	Lower limit	0.82	0.86	0.91	0.96	1.01
99% Confidence Interval with increasing variance	Variance: σ	0.05	0.07	0.10	0.14	0.21
	Upper limit	1.16	1.27	1.40	1.56	1.79
	Lower limit	0.93	0.92	0.89	0.82	0.69

Here, μ is the average of x_n . Then, the likelihood of the simultaneous occurrence of $x = (x_1, x_2 \dots x_n)$ is expressed as equation (4):

$$L(\beta|x) = \prod_{n=1}^{26} f(x_n) \quad (4)$$

The value of β_0 and β_1 are obtained by numerical solution to maximize the value of $L(\beta|x)$. The confidence interval of C_R are expressed as follows:

$$\text{Upper limit: } C_R = \alpha x_n + \delta + \beta_2 \sigma_n \quad (5)$$

$$\text{Lower limit: } C_R = \alpha x_n + \delta - \beta_2 \sigma_n \quad (6)$$

Here,

- α : Gradient of C_R
- δ : Y-intercept of C_R
- β_2 : Confidence of variance of normal distribution
- σ_n : Variance of C_R defined by equation(2)

The standard manufacturing tolerance is 0.9 to 1.1. Ueda et al.⁵⁾ reported the statistic average was 0.997 with 0.031 standard variance. This means 99% confidence interval is from 0.917 to 1.077. Assuming the initial C_R is 0.997 and the limit is from 0.917 to 1.077 at the time of delivery of fenders, the values of β are in **Table 6**. **Table 7** shows the characteristics values of the reaction force coefficient: C_R by service years. Focusing on the 30 service years after which all fenders were non-usable as shown in **Fig.4**, the average increase in reaction force is +14% and 99% upper limit is +37% and 40%, while the lower limit is -9% and -11% at 30 years, respectively in **Table 7**. The increasing variance varies in a wider range than the conventional constant variance method after 30 years. Note that each plot still has $\pm 10\%$ variance from catalogue value due to the manufacturing tolerance.

(5) High reaction force “re-hardening” after a long interval

Vulcanization is the condition in which the rubber gets high elasticity by sulfur crosslinking between polymer molecules. Some of the links are weaker than others and easily cut when they are stretched. The PIANC 2002 guidelines⁶⁾ require that the newly vulcanized fender must be compressed three times in which the first compression is to cut the insufficient links between rubber molecules. This is called the stress relaxation compression and this performance data is not used. In **Table 2**, the first compressions after returning from site are showing to be significantly higher than the average of second and third reaction forces. The first compression’s high reaction

force was considered to have been eliminated by the stress relaxation compression when it was manufactured. This increase in reaction force looks like “restoration” after a long interval. The mechanism in the fender performance has not been clarified yet but the chemical phenomenon was first reported by Mullins⁷⁾ who stated that the recovery rate towards the initial properties differed by temperature and compoundings of rubber. The recovery speed is very slow in normal temperature. It is not likely that the recovery exceeds the initial properties, thus this re-hardening could be the combination of the recovery after an interval and the material hardening by age. As shown in **Table 2**, the reaction force of 800H with 45% increase after 25 years, and the 30% increase for the 1600H after only 10 years cannot be ignored with respect to the berth structure and ship hull strength even though it applies to the first compression only. The duration from the latest berthing to the compression test were unknown for the fenders in **Table 2**. Generally, fenders are likely to be compressed within a week or one month. However, some countermeasures such as controlling the berthing velocity, or extra compression at the manufacturer’s facility might be considered for some cases such as the re-use of inventory fenders.

4. MATERIAL TESTS

The following five returned fenders out of **Table 1** were cut to take out the rubber blocks:

- FD No. 3 : 1450H after 14 years
- FD No. 8 : 800H after 25 years
- FD No. 9 : 1700H after 27 years
- FD No.10: 2000H after 30 years
- FD No.11: 3000H after 32 years

The material samples of 2mm thickness were made by slicing the rubber blocks in order to see how aging affects the thick rubber wall. This procedure is illustrated in **Fig.5**. The upper side had been facing the sky and the lower side had been facing down to the sea water.

(1) Test procedure

Samples are tested by the following procedure found in the Japanese Industrial Standards:

- Hardness(deg): JIS K6253-3 Type A
- Tensile strength(MPa): JIS K6251 Type 3
- Elongation at break(%): JIS K6251 Type 3

(2) Profile of material properties

As the example of material test results, the distribution of material properties of FD No.11 are shown in **Fig.6**. The Y-axis represents hardness and tensile




Fig. 5 Rubber sampling from returned fenders.




Fig.6 Distribution of material properties of FD No.11: 3000H(R0-10) after 32 years.

strength (measured in MPa). The second Y-axis represents the elongation breaking point (measured in %). The X-axis represents the depth from outer surface, hence 0mm is the outer surface and 495mm (Ex. FD No.11:3000H) means the inner surface of the hollow cylinder. The solid lines with solid plots show the data obtained at the upper side and the broken lines with empty plots show the ones obtained at the lower side. Both look similar except that about 10 mm of outer surface where the elongation breaking point of the upper side is lower than that of the lower side. The effect of sunlight is shown only in the upper side surface. Rubber deteriorates from the surface by the effects of sunlight, heat, oxygen, ozone, and so on. It starts from the surface and makes the rubber stiff and brittle and resulting in higher hardness, lower tensile strength, and shorter elongation. Itoh et al.⁸⁾, defined two regions of rubber from the used bridge bearing: outer and inner, and reported that the




Fig.7 Aging of modulus of inner region: (Average tensile strength) / (Average elongation at break).




Fig.8 Distribution of material aging coefficient: FD No.11 3000H(R0-10), 32 years, Upper side.

property in the outer region deteriorates but does not extend to the inner region. The thickness of the outer region is called the critical depth: d_c which is proportional to the exponent of reciprocal of temperature as shown in equation (7):

$$d_c = \alpha_c \exp\left(\frac{\beta_c}{T}\right) \quad (7)$$

Here,

- d_c : Critical depth (mm)
- α_c : Constant ($=8.0 \times 10^{-4}$ mm)
- β_c : Constant ($=3.3 \times 10^3$ K)
- T : Absolute temperature (K)

In **Fig.6**, the critical depth is approximately 70mm from both the outer and inner surface of the body. As shown in **Table 1** and **Table 2**, FD No.11 was evaluated “Non-usable” because it could not be tested properly due to the cracks and uneven buckling. However, the physical properties of the inner region,




Fig.9 Elongation coefficients of returned fenders near surface (Upper side).

as shown in **Fig.6**, shows little deterioration. The service life of this fender may have been affected by the operational conditions rather than the material aging; therefore, a longer serviceable life may have been achieved if a different operational method was used. The initial value of rubber properties has a wide range of deviation due to the following facts:

1. Type of rubber grade compound
2. Manufacturing variance
3. Variance of cut sample quality from fender
4. Minor changes to recipe made in the past
5. Difference in vulcanizing condition between sample sheet and actual product.

For reference, the example of modulus (Tensile strength/Elongation at breaking point) in relation to service years is shown in **Fig.7**. The modulus plots of each year are the sampling depths, which mean values of the inner region of the fender rubber bodies. The values at year 0 are the record of the quality test when manufactured. The rubber compounding has been modified a couple of times in the past thus it varies in the range of about 20%. Though the inner part of the rubber has no exposure/contact with oxygen, **Fig.7** indicates a moderate increase and **Fig.4** indicates an increase in reaction force. The variance of material also affects the variance of reaction force. The reason being that the free sulfur slowly re-entangles in links at normal temperature without the supply of oxygen. In order to discuss the aging impact of rubber, the material aging coefficient is used by dividing the property data (hardness, tensile strength, and elongation at breaking point) by the average value of the inner region. **Fig.8** is the material aging coefficient of FD No.11. Modulus in the outer region rises as it approaches the surfaces. **Fig.8** suggests that the coefficient of elongation at breaking point shows the distribution most clearly. Then, the comparison with other fenders are shown in **Fig.9**. Sueyasu⁹⁾ reported

the deterioration of 14 years in north Japan penetrated 20 to 30mm. This is smaller than 70 mm in **Fig.6** and **Fig.8**. The difference in average temperature between the north area and FD No.3 in the south island is about 15°C³⁾ which might be the reason for this difference in elongation coefficient. The calculated critical depths by Itoh et al⁸⁾ at each site location are shown in **Fig.9**. They look close to the measured distribution of FD No.8, 9, 10, and 11 (from 55 to 74mm) in **Fig.9** except for the 3000H-14 years in the north area where the critical depth is 102mm. Since the density of the data at the boundary between outer and inner region is insufficient, the exact critical depth cannot be clearly declared. However, in the coastal condition of Japan's climate, the average critical depth appears to be around 70 mm. The distribution of deterioration becomes flat at the area deeper than the critical depth. Thus, the material life is considered "still usable" after 30 years of service. On the other hand, smaller fenders (Ex. body thickness<140mm) will have more deterioration in the whole body. This is also suggested in **Table 2** which shows that smaller fenders have higher reaction forces.

It would be convenient if we could take a small rubber sample from the fender surface on a quay wall and evaluate the aging non-destructively. However, the above material tests indicate that it would be difficult because the aging at surface and its penetration may not be a simple reaction linear to time and temperature.

5. CONCLUSIONS

- (1) The service years of the Circular-Shaped Buckling fender from the supply record was about 15 years to 35 years.
- (2) The compression tests of the returned Circular-Shaped Buckling fender showed that all fenders over 30 service years had lost their normal performance. There was a moderate increase in reaction force by service years but the effect of cracks and uneven buckling mitigated this increase.
- (3) The rubber deterioration progressed by service years and by high temperature climate. It was limited within the critical depth, which was around 70mm from the surface and the deterioration of inner region was little even after 32 years. The small fenders had more aging impact

than large fenders.

- (4) The compression tests of returned fender indicated that, after returning from site, the first compression may have had a higher reaction force than the initial value used for the design load.

This study was conducted only on CSB fenders. If the basic material and function were the same, then we would suggest that the aging effects will be similar to other types of fenders with frontal panel. However, quantitative data such as number of years and material property changes will be needed to confirm this.

ACKNOWLEDGMENTS: The authors would like to thank Dr. N. Murota, N. Yamaguchi, S. Kajigaya, and other members of Bridgestone Corporation for their continuous support in the gathering and disclosing of old and precious records. They also thank Prof. K. Kaito of the Department of Civil Engineering and Mr. Y. Ninomiya of the Graduate School of Engineering, Osaka University for their precious advice in the statistic data processing.

REFERENCES

- 1) Terauchi, K., Koizumi, T., Yamamoto, S. and Hosokawa, K.: The Deterioration actual state and the function evaluation on the rubber fender, *Tech. Notes of the Port and Harbor Research Institute*, No. 878, 1957. (in Japanese)
- 2) CDIT: Gomubougenzai no Ijikanri Guideline, *Coastal Development Institute of Technology Library*, No.40, Mar. 2013. (in Japanese)
- 3) Japan Meteorological Agency: <http://www.data.jma.go.jp/gmd/cpd/cgi-bin/view/index.php>, Accessed June 29, 2015.
- 4) Japan section of PIANC: Report of the Japanese commission for the design of fender systems, *Permanent International Association of Navigation Congress*, pp. 122-124, Mar.1980. (in Japanese)
- 5) Ueda, S., Umemura, T., Shiraiishi, S., Yamamoto, S., Akakura, Y. and Yamase, S.: Toukeiteki Syuhou niyoru Senpaku Setsuganyou Bougenzai no Sekkei nikansuru Kenkyu, *Proceedings of Coastal Engineering, JSCE*, Vol. 47, pp. 866-870, 2000. (in Japanese)
- 6) MarCom Working Group 33: Guidelines for the design of fenders system, *International Navigation Congress*, 2002.
- 7) Mullins, L.: Effect of stretching on the properties of rubber, *Journal of Rubber Research*, Vol. 16, pp. 275-289, 1947.
- 8) Itoh, Y., Gu, H., Satoh, H. and Kutsuna, Y.: Long-term determination of high damping rubber bridge bearing, *Doboku Gakkai Ronbunshyu A*, Vol. 62, No. 3, pp. 595-607, 2006.
- 9) Sueyasu, T.: Long term aging and life forecast of large rubber products, *Proc. of 141th Rubber Technology Symposium*, pp. 27-36, 2008. (in Japanese)

(Received August 17, 2016)